### Pick-Off Mirror Controls

## This Sheet information

Note: At A12 to M12 is the Proton box connector drawing and identification.

At A36 to L36 is the P-Bar box connector drawing and identification.


At A68 to K68 is information about the Pick-Off Motor.

At P24 is the color code for the Motor cables.


At M1 to AD1 is information on the cables for the back of the RR at C0.

G6F12 88 3-16-200 connect ХΙ between Nu ΥI Drive and URI ΖI F

#3 Foci



BNC - 1 Ultra Violet Lamp MCI #2 LM F 1. Focus Camera Limit Switchs PICK -2. Resolver #3 (Not Used) SHV To camera MCD Ren. High Voltage for Camera Screen Flip In BNC - 2 To Camera Cathode In BNC - 3 To Camera Cathode Out Υ 3. Y axes Steering Limit Switchs 4. Motor Flip In 5. Motor Y axes steering 6. Motor Camera Focus 7. Resolver X axes steering 8. X axes Steering Limit Switches 9. Flip In Limit Switchs 10. Linear Pot for camera focus 11. Motor X axes steering 12. Resolver Y axes steering



1. Resolver # 1 ( Not Used) 2. Limit Switchs 3 & 4 (Not Used)

lacktriangle3. Resolver # 2 ( Not Used)

Ren -1

BNC - 3

4. Linear Pot for camera focus SHV 1

5. Resolver #3 X axes lacktrian6. Limit Switchs 5 & 6

BNC - 2 7. Focus Camera Limit Switchs

• 8. Motor 1 Camera

9. Motor 4 X axes steering ullet10. Limit Switchs 1 & 2 (Not Used)

11. Motor 2 X axes steering (Not Used)

12. Motor 3 Y axes steering (Not Used)

Ren 1 High Voltage for Camera Screen

SHV 1 To camera

BNC -1 To Ultra Violet Lamp BNC -2 To Camera Cathode In BNC -3 To Camera Cathode Out


7-19-1 Read Back P-Bar 4.94 Proton 5.15 3/13/2002 SYNC LIGHT BOX

## Pick-Off Mirror Controls


20000 counts = 1 inch counts in the - direction runs motor in REV direction. counts in the + direction runs motor in FORWARD direction.

Inner limit P-BAR 19.40 mm 1.09 volts 9.91 volts Power Supply out 0 location (outen) 4.98 volts 10,000 in 3.80 20,000 16 mm 2.71 30,00 15.87 mm--see light 1 volt Comes in 19.94 9.91v on PS V-4.89v pos(mm)= -0.1953 Stuff Alan Hann told Chuck Brown over the phone

If the counts is set to 1000, the motor will run in a FORWARD direction, which is clockwise in drawing below, (viewed from the top), and this will run the mirror in. The pot wiper is moved In the direction of the big arrow, next to the Readback



3 Yellow wire, Positive **P-bar shown** 



SYNC LIGHT BOX 3/13/2002

# Pick-Off Mirror Controls

PNE Pins A	Ą	В	С	D	Ε	F	G	Н	Shield	N. C.	
)0 Motor #1 1	1	2	4	5	3	3	3	3	3		1 Red, 2 Blk, 3 Grn & Shield, 4 Wht, 5 Blk
ENCODER 6	3	5	4	3	2	1			8	7	1 Red, 2 Blk, 3 Grn, 4 Blk, 5 Wht, 6 Blk, 8 Shield
ENCODER 6	3	5	4	3	2	1			8	7	1 Red, 2 Blk, 3 Grn, 4 Blk, 5 Wht, 6 Blk, 8 Shield
ENCODER 6	3	5	4	3	2	1			8	7	1 Red, 2 Blk, 3 Grn, 4 Blk, 5 Wht, 6 Blk, 8 Shield
PICK - OFF 5	5	4	2	1	3	3			3		1 Brn, 2 Org, 3 Shield, 4 Blk, 5 Red
X MOTOR 5	5	4	2	1	3	3	3	3			1 Blk, 2 Wht, 3 Grn & Shield, 4 Blk, 5 Red
Y MOTOR 5	5	4	2	1	3	3	3	3			1 Blk, 2 Wht, 3 Grn & Shield, 4 Blk, 5 Red
#2 MOTOR 5	5	4	2	1	3	3	3	3			1 Blk, 2 Wht, 3 Grn & Shield, 4 Blk, 5 Red
us MOTOR 5	5	4	2	1	3	3	3	3			1 Blk, 2 Wht, 3 Grn & Shield, 4 Blk, 5 Red
LM #1 2 8	3 3	5	1	5	5	5				4	1 Red, 2 Wht & Grn, 3 Grn, 5 Blk & Shield
LM X 3 8	3.2	5	1	5	5	5				4	1 Red, 2 Grn, 3 Wht & Grn, 5 Blk & Shield
LM Y 3 8	3.2	5	1	5	5	5				4	1 Red, 2 Grn, 3 Wht & Grn, 5 Blk & Shield
Focus Limit 3 8	<u> 2</u>	5	1	5		5	5			E & 4	1 Red, 2 Grn, 3 Wht & Grn, 5 Blk & Shield
Flip-In Limit 3 8	3.2	5	1	5	5	5				4	1 Red, 2 Grn, 3 Wht & Grn, 5 Blk & Shield
OFF LIMIT 2 8	3 3	5	1	5	5	5			5		1 Red, 2 Wht, 3 Wht, 5 Blk & Shield

Reasolver Reasolver

Burndy male to Burndy Female Pin A to Pin A and so on.

'Reasolver

Color code for Motor cables

A Vil B Blu C Grn D Yel E Org F Red G Brn H Blk

Org Red

5 Y MOTOR 9 X MOTOR

	Cable #4 Proton Pick Off Y-Axis	I am not sure what this is. 7-23-01, Dale				
Cable #1	A Blk B Brn C Red D Org E Yel F Grn G Shield	A Yel  B Grn  C Blu  E Blk  F Brn  G Shield				
#	A Blu B Vil	A Red B Org # C Yel				
—— 4	C Blk D Brn E Red F Org G Shield	# C Yel G D Gm D E Blu F Vil G Shield				

3/13/2002 SYNC LIGHT BOX

# Pick-Off Mirror Controls

Wires pulled if from downstairs C-0 to the service building @ C0										
Proton	P-Bar	Pick off	total	cond	cables	cond/cable				
4 - limit sw's - 6 cond	2 limit sw's	2 limit sw's	8	48	3 22/10	30				
					3 22/6	18				
						48				
4 - Motors - 6 cond	2 Motors	2 Motors	8	48	5 16/8	40				
					1 16/8	8				
						48				
2 - Resolver - 8 cond	1 Resolver		3	24	3 22/10	30				
1 - Linear Pot - 3 cond	1 Linear Pot	2 Linear Pot	4	12	2 22/6	12				
4 Disc Males	4 B' . M. (			•	4 00/0					
1 Pico Motor	1 Pico Motor	need tota	1_	6 138	_1 22/6	6				
Spare cables		need tota	ai cond. =	130	1 16/8	8				
Spare cables						6				
					1 22/6	O				
	Org. addi	tional								
total cables		1 7	22/6	42						
total cables		6 6	22/10	60						
	-	2 7	16/8	54						
			al cond. =	156	_					
		20 1010	ai 00110. –	.50						